Improvements to miniDAWN® and microDAWN™ (NEON) Firmware

INTRODUCTION

This document highlights the most important enhancements, changes, and bug fixes made to the Wyatt Firmware. Please contact us at support@wyatt.com if you have any questions or suggestions.

CONTENTS

| Introduction | 1 |
|----------------------------|---|
| Version History | 2 |
| 4.0.6 | 2 |
| Improvements and Bug Fixes | 2 |
| 4.0.5 | 2 |
| Improvements and Bug Fixes | 2 |
| 3.2.10 | |
| Improvements and Bug Fixes | 2 |
| 3.2.8 | |
| Improvements and Bug Fixes | 2 |
| 3.2.6 | |
| Improvements and Bug Fixes | |
| 3.2.5 | |
| Improvements and Bug Fixes | |
| 3.2.4 | |
| Improvements and Bug Fixes | |
| 3.2.2 | |
| Initial Release | |

VERSION HISTORY

4.0.6

Improvements and Bug Fixes

- **Fixed:** Installer would sometimes hang when trying to find instruments on the network. (D-19715)
- **Fixed:** Installer would not properly report out of disk space error. (D-19559)
- **Fixed:** Some communication settings were not preserved after a reboot. (D-19163)

4.0.5

Improvements and Bug Fixes

- **Fixed:** The firmware updater has been made more reliable. (S-19000)
- **Added:** Added a SATA drive health monitor. (S-18673)

3.2.10

Improvements and Bug Fixes

• **Changed:** Optimized logging by the firmware. (D-18218)

3.2.8

Improvements and Bug Fixes

• **Added:** A lock button is now visible in the top corner of the front panel, which allows users to toggle a lock feature that disables touch screen input and dims the screen.

3.2.6

Improvements and Bug Fixes

• **Added:** A security update to further ensure that your instrument is not susceptible to network-based malware. (TT#19698)

3.2.5

Improvements and Bug Fixes

- **Fixed:** The laser now turns back on after the hood is closed during a collection. (TT#18765)
- **Fixed:** Warn the user that the laser cannot be turned on for thirty seconds after DLS is turned off. (TT#18809)

3.2.4

Improvements and Bug Fixes

- **Added:** The main graph on the front panel now has an auto-scale button. (S-05872)
- **Updated:** The health indicators are disabled when the laser interlock alarm is triggered and are reinitialized when the alarm is turned off. (D-05396)
- **Updated:** The graphs on the front panel automatically scroll when zoomed in if there are more than two hours of data. (S-05590)
- **Fixed:** Addressed an issue where the temperature displays -50C when the temp probe is disconnected. It now displays an appropriate message. (D-03228)
- **Fixed:** Addressed an issue where the log database can be corrupted when requested by CheckPlus. (D-01505)
- **Fixed:** Addressed an issue where the laser will go into idle mode when it is switched off instead of turning off. (D-03520)
- **Fixed:** Addressed an issue where the validation of custom axis scales can be wrong on the front panel when modified. (D-03321)

Fixed: Addressed an issue where the values for parameters on the front panel can display the wrong data. (D-03253)

3.2.2

Initial Release

Copyright © 2023 Wyatt Technology Corporation. All rights reserved.

Please contact Wyatt Customer Support if you need more information about changes in earlier versions of the firmware.